

Firmware Release Notes

NF18ACV – VDSL/ADSL2+ Dual Band AC1600 Gigabit Gateway with VoIP



Copyright

Copyright© 2026 NetComm Wireless Pty Limited. All rights reserved.

The information contained herein is proprietary to NetComm Wireless Pty Limited. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of NetComm Wireless Pty Limited.

Trademarks and registered trademarks are the property of NetComm Wireless Pty Limited or their respective owners. Specifications are subject to change without notice. Images shown may vary slightly from the actual product.



Note – This document is subject to change without notice.

Document history

This document covers the following product:

NetComm Wireless NF18ACV – VDSL/ADSL2+ Dual Band AC1600 Gigabit Gateway with VoIP

VER.	DOCUMENT DESCRIPTION	DATE
v1.0	Initial document release	6 November 2017
v1.1	Details change to releases NC2-R6B012 and R6B016	18 December 2018
v1.2	Details change to release NC2-R6B013	23 May 2019
v1.3	Details change to release NC2-R6B014	27 August 2019
v1.4	Details change to release NC2-RB6017	12 February 2020
v1.5	Details change to release NC2-RB6021	26 November 2020
v1.6	Details change to release NC2-RB6022	21 December 2020
v1.7	Details change to release NC2-RB6023	17 September 2021
v1.8	Details change to release NC2-RB6024	10 November 2023
V1.9	Details change to release NC2-RB6025	10 February 2026

Table i. - Document revision history

Contents

Firmware Details	4
Version History	4
NC2-R6B025	4
Enhancements	4
NC2-R6B024	4
Enhancements	4
NC2-R6B023	4
New Features	4
Enhancements	5
NC2-R6B022	5
Enhancement	5
NC2-R6B021	5
New Features	5
Enhancements	5
NC2-R6B017	6
New Features	6
Enhancements	6
NC2-R6B014	7
Enhancements	7
NC2-R6B013	7
New Features	7
Enhancements	7
NC2-R6B012	7
New Features	7
Enhancements	8
R6B016	8
New Features	8
Enhancements	8
R6B015 – Initial production release	8
New Features	8
Enhancements	8




Firmware Details

ITEM	DESCRIPTION
Model	NF18ACV
Product Name	VDSL/ADSL2+ Dual Band AC1600 Gigabit Gateway with VoIP
Date	10 February 2026
Firmware Version	NF18ACV-NC2-R6B025
Official / Beta Firmware	Official
File Name	NF18ACV-NC2-R6B025.EN_Upgrade.w
File Size	32 MB
MD5 Checksum	204674bd14a8ec04fdb96cd344eda029

Version History



NC2-R6B025

Enhancements

-  Updated for Security vulnerability. (TT 45568, 45571, 45565)
-  Fixed a 2.4GHz Guest Wi-Fi authentication incorrectly remained set to “Open” after changing to “WPA2-PSK”. (TT 45263)
-  Fixed cosmetic UI issue on the 2.4GHz and 5GHz Wireless Advanced Settings pages. (TT 45208)



NC2-R6B024

Enhancements

-  Updated firmware to check both primary and secondary DNS for keep-alive before sending DHCP discovery (TT 45143)
-  This update addresses a security vulnerability (TT 44047)

NC2-R6B023

New Features

-  Added capability to route traffic from a source address different from the LAN subnet (TT 24320)
-  Added capability to switch calls using a flash key (TT 38096)

- Added patch for WiFi Krook security (TT 40389)
- Added information on webUI for connection uptime (TT 41584)
- [IPv6] Default Router Preference should be Medium and must include PIO (TT 41986, TT 41988)
- [IPv6] ULA with "Randomly Generate" enabled by default (TT 41987)
- [IPv6] RA default lifetime set to 1800 seconds per RFC4861 (TT 41989)
- Added a patch to address FragAttack vulnerabilities (TT 42262)
- Enabled SOS (Save Our Showtime) and RoC (Robust Overhead Channel) (TT 42302)

Enhancements

- WebUI enhancements (TT 24672, TT 39138, TT 41336, TT 41379)
- Fixed a date and time issue for VoIP calls (TT 20442)
- Fixed an issue where telnet showed time in UTC (TT 39869)
- Fixed the incorrect displays of MTU size and MSS size (TT 41132)
- Fixed an issue with DHCP static leases rule getting deleted after upgrade (TT 41583)
- Fixed an issue where IP filter is not working with subnet (TT 42282)
- Fixed an issue with IPv6-PD drop issue (TT 42310)
- Fixed an issue with QoS classification showing wrong queues (TT 42322)

NC2-R6B022

Enhancement

- Fixed an issue with the default 2.4GHz/5GHz key and password issue (TT 41586)









NC2-R6B021

New Features

- Added hook and call status on the SIP page (TT 39464)


















Enhancements

- Disabled Service in access control by default including SSH, Telnet, SNMP, Samba (TT 40589)
- Cosmetic updates on the QoS Classification page (TT 40488, TT 40487, TT 40473)
- Cosmetic update on the Password page (TT 40417)
- Cosmetic update on the Wizard page (TT 40722)
- Fixed a wizard issue where it would not save the VPI/VCI value if it was not 8/35 (TT 40158)
- Cosmetic updates to the DHCP option page and SIP settings (TT 39344)
- Enhanced the performance of the web user interface (TT 39434)





-  Fixed an issue where applying changes remotely always shows a blank page (TT 39253)
-  Fixed an issue with Port forwarding rules not correctly showing their WAN interface (TT 39807)
-  Fixed an issue where Hide SSID on the 2.4GHz radio could not be turned off after it was turned on (TT 39684)
-  Updated the ETH WAN interface default settings to “No VLAN” and “Dynamic IP” (TT 41423)
-  Updated the VDSL interface default settings to “No VLAN” and “Dynamic IP” (TT 41422)
-  Fixed Guest Wi-Fi password issue when the password is less than 8 characters (TT 41149)
-  Added iperf3 support (TT 40154)
-  Enhance CPE security (TT 41415)

NC2-R6B017

New Features


-  Added a check to validate any incorrect input for Static IP DNS addresses (TT 26078)
-  Added support to enable /disable the Firewall in a created interface (TT 38331)
-  Added support to enable /disable access for HTTPS via the Access Control page (TT 38739)
-  Added support to allow username containing 5 or more special characters (TT38367)
-  Updated default setting with QoS classification enabled by default (TT 38432)
-  Added support to log in to the device remotely via HTTPS (TT 38738)
-  Updated the default setting of the RX Chain power save on the 2.4/5GHz to be disabled by default (TT 39134)
-  Added the ability to edit any created port forwarding rule (TT 39109)
-  Added the ability to edit any created port triggering rule (TT 39143)
-  Added the ability to edit any created MAC filtering rule (TT 39144)
-  Added the ability to edit any created QoS Classification rule (TT 39145)
-  Added the ability to edit any created incoming and outgoing IP filtering rule (TT 39147)
-  Added the ability to edit any created DDNS rule (TT 39148)
-  Added the ability to edit any created IPsec interface (TT 39150)
-  Added the ability to edit any created QoS Queue rule (TT 39146)
-  Added an option to hide SSID for both 2.4GHz and 5Ghz Wi-Fi (TT 39242)
-  Added support to turn on/off the LED under advance setting (TT 20900)

Enhancements

-  Fixed an issue where reboot option was not able to trigger on a different WEB Page (TT 38357)
-  Fixed an issue where user was unable to change the Static DNS on the VDSL interface (TT 38374)
-  Fixed an issue where the advanced menu is missing if browser is accessed from a mobile device (TT 39026)
-  Fixed the intermittent CPE ring-back tone issue (TT 39116)




NC2-R6B014

Enhancements














-  Improved Wi-Fi performance (TT 39023)

NC2-R6B013

New Features





-  Added HTTP link on the firmware version to direct to NetComm NF18ACV firmware page (TT 24765)
-  Added HTTP link to “Visit NetComm Wireless Support Website” (TT 24764)
-  Added special character support on the username/password fields (TT 26481)

Enhancements

-  Updated 2.4GHz and 5GHz Wi-Fi Driver (TT 37972)
-  Updated Wi-Fi default settings (TT 37982)
-  Updated the dial plan to cover the 13[1-9]XXX series (TT 37823)
-  Updated the VoIP DTMF rely to RFC2833 by default (TT 26328)
-  Fixed a stability issue with IPv6 connection (TT 26375)
-  Fixed an issue where DLNA reverts to disabled after the device is power cycled (TT 26121)
-  Fixed an issue where a 31-bit subnet could not be setup on VDSL I PoE via the basic setup page (TT 25903)
-  Fixed an issue where the device displayed an invalid session key message when the HTTP port was changed from the default setting. (TT 37905)
-  Fixed an issue where only 32 entries could be entered on the Parental control page (TT 26327)
-  Fixed an issue where the device cannot return the Wi-Fi Noise floor value (TT 37962)
-  Fixed an issue with TR-069 parameters not reporting Currentlocaltime correctly (TT 38037)
-  Fixed an issue where DHCP option 66 does not support more than 45 characters (TT 37907)
-  Fixed a typo on the wizard setup (TT 24332)

NC2-R6B012

New Features

-  New format for the gateway’s web-based Graphical User Interface (GUI). (TT 20224)
For details on all the new WEB GUI changes, please refer to the latest [NF18ACV User Guide \(UG01040 v1.2\)](#)
-  Configurable TR_069 port field added to Connection Request Authentication settings. (TT 22416)
-  Adjusted the band steering behaviour. (TT 20593)
-  Reduced the volume and used softer tone on the call waiting alert tone. (TT 21747)

- Reduced the frequency of sending SIP registration packets from every 2 seconds to every 5 minutes after receiving an error code 404. (TT 22876)
- Added support for entering TR-069 parameters for SNMP TrapIPAddress. (TT 22160)
- Adjusted the default SIP dial plan settings. (TT 21935)
- Adjusted the SIP dial tone. (TT 20911)
- Adjusted the Serial number of the inventory information to return the correct value. (TT 25325)
- Improved the 2.4GHz Wi-Fi performance. (TT 23538)

Enhancements

- Fixed the DSL LED so that it does not continue to blink even though there is no physical connection to the DSL port. (TT 20310, TT 21780)
- Fixed the Internet LED to only turn on when there is a functioning internet connection. (TT 20508)
- Updated the TR-69 Hardware version to the correct output value. (TT 19450)
- Fixed an issue the CPE become not responsive when changing the PPPoE username via the WEB GUI remotely. (TT 22306)
- Fixed an issue where the CPE is occasionally not able to respond to TR_069 provisioning. (TT 23071)
- Fixed an issue with port forwarding not able to apply on the same port that is used on the Access control page. (TT 19487)
- Fixed an issue with WAN port acting as LAN during start-up. (TT 21151)

R6B016

New Features

- Added an automatic firewall to block unsolicited VoIP traffic.

Enhancements

- Fixed a problem where automatic Wi-Fi channel selection could not be enabled/disabled via TR-069.
- Improved an issue with Wi-Fi throughput when country code was set to "NEW ZEALAND".
- Fixed an issue with priority marking on VoIP packets.

R6B015 – Initial production release

New Features

- None.

Enhancements

- None.