

# Firmware Release Notes

## CloudMesh Gateway – NF20MESH



Doc No. FR01347

## Copyright

Copyright© 2022 Casa Systems. All rights reserved.

The information contained herein is proprietary to Casa Systems. No part of this document may be translated, transcribed, reproduced, in any form, or by any means without prior written consent of Casa Systems.

Trademarks and registered trademarks are the property of Casa Systems or their respective owners. Specifications are subject to change without notice. Images shown may vary slightly from the actual product.

Previous versions of this document may have been issued by NetComm Wireless. NetComm Wireless Limited was acquired by Casa Systems in 2019.



**Note** – This document is subject to change without notice.

## Document history

This document contains Release Notes for following product:

### NetComm CloudMesh Gateway – NF20MESH

Ver.	Document description	Date
v1.01	Initial document release	18 June 2021
v1.02	Includes changes to release no. R6B021	3 August 2022
v1.03	Includes changes to release no. R6B025	11 November 2022
v1.04	Includes changes to release no. R6B026	29 March 2023

*Table 1. – Document revision history*

## Firmware details

ITEM	DESCRIPTION
Model	NF20MESH
Product Name	CloudMesh Gateway
Date	29 March 2023
Firmware Version	NF20MESH.NC.UR-R6B026
Official / Beta Firmware	Official
File Name	NF20MESH.NC.UR-R6B026.EN_Upgrade.w.enc
File Size	43 MB
MD5 Checksum	4F052FD1DC607D79B39C1984CA2C8526

## Version history

### R6B026

#### New Features

- Added Support for TR069 Parameter Device.DeviceInfo.DeviceLog (TT 42287)

#### Enhancements

- Fixed an issue where device was not reporting "8-Diagnostics Complete" when an invalid IP address is used for TR069 IP ping test (TT 43851)
- Fixed an issue where WebUI was locking up in certain scenarios (TT 44041)
- Fixed an issue where disabling any WAN access service required a reboot in order for the disablement to take effect (TT 44071)
- Fixed an issue where static IP lease was displaying only 4 entries (TT 43727)
- Fixed an issue for WPS WebUI soft button (TT 43772)
- Update mesh agent version to 02.02.82.02-1502 (TT 44445)
- Fixed an issue where clients were observing drops when a configuration where mesh is disabled is restored (TT 44028)

- Updated firmware to reflect correct system uptime using SNMP (TT 44036)
- Fixed an issue where SIP ALG enable/disable had no effect (TT 44077)

## R6B025

### Enhancements

- This update addresses a critical security vulnerability (TT 44047)

## R6B021

### New Features

- Added an option to disable 802.11ax on 2.4GHz to allow non-compatible clients to connect (TT 42824)

### Enhancements

- Updated IPv6 ULA preferred, and valid lifetime (TT 41995)
- Fixed an issue where DDNS connection was not getting established when using password with special characters (TT 42209)
- WebUI enhancements (TT 42223, TT 42233, TT 42234, TT 42360, TT 43545)
- Fixed an issue of IPv6-PD drop after few days (TT 42225)
- Updated TR-069 formula for parameter Device.IP.Diagnostics.UploadDiagnostics.Bandwidth to reflect correct upload bandwidth (TT 42227)
- Fixed an issue where CPE was unable to set Pbit to 5 for SIP and RTP traffic (TT 42231)
- Fixed an issue where user was unable to delete all the entries of port forwarding at once (TT 42235)
- Updated WebUI to reflect correct auto -channel status when changed using TR-069 (TT 42251)
- Added patch for FragAttack vulnerability (TT 42272)
- Fixed an issue where user was unable to delete all the entries of port triggering at once (TT 42235)
- Updated TR-069 default setting (TT 42328)
- Updated TR-069 formula for parameter Device.IP.Diagnostics.DownloadDiagnostics.Bandwidth to reflect correct download bandwidth (TT 42604)

- Fixed an issue where CPE was not allowing to create same QoS rule on 2 different services on different interface (TT 42629)
- Updated LAN secondary DNS to blank (TT 42860)
- Fixed an issue where CPE was not sending IPv6 Solicit when uplink connection is down for long duration (TT 42872, TT 42873)
- Fixed an issue where PPPoE was not sending discovery after disconnection (TT 42875)
- Fixed an issue where TR-143 TotalBytesReceived was reported as "0" (TT 42991)
- Updated CPE behaviour where user was unable to login when changing to Username of length 16 Characters (TT 43026)
- Updated SNMP remote settings (TT 43516)
- Updated default Wi-Fi encryption to Mixed WPA 3-SAE/WPA2-PSK (TT 43520)
- Updated default setting of ULA to randomly generate (TT 43531)
- Updated default IPv6 router preference to "Medium" as per RFC 4191 (TT 43537)
- Updated Router Advertisement(RA) on LAN to include Prefix information option (PIO) & RDNS options (TT 43543, TT 43550)
- Updated Router Advertisement(RA) Route Information Option preference to "high" (TT 43551)

## R6B019 – Initial production release

### New Features

- None

### Enhancements

- None