Information

NetComm Product Name	NP805N
NetComm Product Description	11n Wireless Gigabit Router
Firmware Version	R0.05b8-05020945
Official / Beta Firmware	Official
File Name	**20130502_Netcomm_NP805N_R0.05b8-05020945.bin**
File Size	6.84 MB
MD5 Checksum	8AEA1EC07863E4B75267643C035F5DEF
Date	8 May 2013

Upgrade Instruction

1. Plug the power adapter and press the Power button at the back of NP805N to turn On the NP805N.
2. Allow 60 – 90 seconds for the NP805N to power up.
3. Connect your computer to any Ethernet port on the NP805N.
4. Open the web browser (Internet Explorer, Firefox, etc) on the computer, type in http://192.168.20.1 on the address bar, then press **Enter**.
5. Type in the System Password (the default one is *admin* for both Username and Password) then press **Login**.
6. Click **Toolbox** and then click **Firmware Upgrade** on the top menu.

7. Press the **Browse** button and load the firmware (**20130502_Netcomm_NP805N_R0.05b8-05020945.bin**).
8. Click **Upgrade** to proceed. It will take a few minutes to proceed upgrading until the router reboots itself.
9. Once the upgrade is done, you will be brought into Login page. Type in the System Password (the default one is *admin* for both Username and Password) then press Login.

NetComm Wireless Limited ● 18-20 Orion Road, Lane Cove NSW 2066, Sydney Australia
t +61 (2) 9424 2000 f +61 (2) 9424 2010 ● www.netcommwireless.com ● ACN 002 490 486

10. Click **Toolbox** and then click **Firmware Upgrade** on the top menu.

11. Make sure the current firmware version is **R0.05b8-05020945**.
12. Click **Reset to Default** under the **Toolbox** menu.

Warning: Resetting the router to defaults is required in order for the router to function correctly after firmware upgrade.

New Features

R0.05b8-05020945

1. Added SIP ALG option which is located under Toolbox > Miscellaneous menu
2. Added DHCP Option 66 feature

Bug Fixes

R0.05b8-05020945

1. Fixed compatibility issue with Internet Explorer 10
2. Fixed NAT loopback issue

Known Issues

R0.05b8-05020945

1. None

NetComm Wireless Limited ● 18-20 Orion Road, Lane Cove NSW 2066, Sydney Australia
t +61 (2) 9424 2000 f +61 (2) 9424 2010 ● www.netcommwireless.com ● ACN 002 490 486

Version History

R0.05b5-11271130

- New Features
  None
- Bug Fixes
  1. Fixed broadcast unnecessary traffic on WAN side
  2. Fixed VLAN tagging issue
  3. Fixed IP address leakage of the devices behind the NAT through WAN PPPoE connection
- Known Issue
  None

R0.05b0_08230940

- New Features
  None
- Bug Fixes
  1. Fixed throughput issue
  2. Fixed the Web User Interface browsing issue on touch-based devices
  3. Fixed cosmetic issues on the Web User Interface
- Known Issue
  None

R0.05a6

- New Features
  1. IGMP Snooping
- Bug Fixes
  1. Fixed cosmetic issues on Web User Interface
- Known Issue
  None

R0.05a4 – Initial production release

- New Features
  None
- Bug Fixes
  None
- Known Issue
  None

NetComm Wireless Limited ● 18-20 Orion Road, Lane Cove NSW 2066, Sydney Australia
t +61 (2) 9424 2000 f +61 (2) 9424 2010 ● www.netcommwireless.com ● ACN 002 490 486